




# SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS  
OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

<b>SERVICE BULLETIN</b>		No.: MSB-97E52-503	
		Date: 1998-04-15	<b>&lt;Model&gt;</b> (EC,EXP) GALANT (EA0)
<b>Subject:</b> CORRECTION TO METER BEZEL REMOVAL		<b>&lt;M/Y&gt;</b> 97-97	
<b>Group:</b> INTERIOR	<b>Draftno:</b> 97-JY-031		
<b>INFORMATION</b>	OVERSEAS SERVICE DEPT	 R. USAMI - MANAGER QUALITY INFORMATION ANALYSIS	

## 1. Description:

This Service Bulletin informs you that the number of metal clips for the meter bezel should have been four, not two.

## 2. Applicable Manuals:

Manual	Pub. No.	Language	Page(s)
'97 GALANT Workshop Manual	PWDE9611	(English)	52A-4
	PWDS9612	(Spanish)	
	PWDF9613	(French)	
	PWDG9614	(German)	
	PWDD9615	(Dutch)	
	PWDW9616	(Swedish)	


## 3. Details:

'97 GALANT Workshop Manual, page 2

**CAUTION: SRS**

For the passenger side air bag module removal/Installation, always observe the service

procedures of GROUP 52B - Air Bag Module and Clock Spring.

**NOTE**

← : metal clip position

**Removal steps**

1. Hood lock release handle
2. Switch bezel
3. TCL switch or auto-cruise control main switch
4. TCL switch or plug
5. Headlamp levelling switch
6. Lower cover
7. Column cover
8. Meter bezel
9. Combination meter
10. Door mirror control switch
11. Fog lamp switch
12. Side air outlet assembly (L.H.)
13. Centre air outlet assembly
14. Side air out

15. Astray
  - Floor console panel (Refer to P.52A-7)
16. Centre console panel
17. Sunglasses box
18. Radio and tape player
19. Heater control assembly (Refer to GROUP 55 - Manual air conditioner)
20. Rear window defogger switch
21. A/C switch
22. Inside/Outside air changeover switch
23. Air conditioner control panel and ECU assembly